

Fig. 1







Fig. 2






Fig. 4

5/9




Fig. 5a




Fig. 5b

6/9




Fig. 6a




Fig. 6b




Fig. 7

8/9

Service: San Fransisco service, Band: 4 Channel 1 208 Service has 4 alarms currently active **Summary:** There are 0 equipment faults on this service Node 10.1.10.2, slot 4, port 1, channel ids 321, 654 are missing Node 10.1.10.2, slot 4, port 1, unexpected channel ids 123, 456 Node 10.1.10.2, slot 5, port 1, channel ids 432, 765 are missing Node 10.1.10.2, slot 5, port 1, unexpected channel ids 234, 567 **Recommendations:** Check cabling on node 10.1.10.2, port 1 of slot 4 and port 1 of slot 5

Fig. 8

